


CALTRANS NEWS RELEASE

Date: Monday, September 27, 2004 #04-109
District: District 2 - Redding, www.dot.ca.gov/dist2

Brian Crane, District Director

Contact: Michael Mayor – <u>michael_mayor@dot.ca.gov</u>

Phone: 530-225-3260

FOR IMMEDIATE RELEASE

Pulga Bridge to be Closed During Night Time Hours

REDDING – The California Department of Transportation (Caltrans) is completing the final phase of rehabilitation work on the Pulga Bridge, which will require complete, night time closures of State Route (SR) 70 in the Feather River Canyon. The work on the Pulga Bridge is part of a three-year project to rehabilitate five bridges along SR 70 in the canyon. Bridges are located at Pulga, Rock Creek, Storrie, Tobin and Howells. Work includes replacement of bridge decks, seismic retrofitting and bridge strengthening, foundation strengthening, upgrade of bridge rail, guardrail and concrete barrier.

Beginning October 18, 2004 the <u>PULGA BRIDGE will be CLOSED</u> during weeknights for deck replacement work. These evening closures are scheduled for 8:00 p.m. to 6:00 a.m., Monday through Friday. The bridge will be open to normal traffic weekdays from 6:00 a.m. to 8:00 p.m. and Saturday mornings beginning at 6:00 a.m. until Monday evenings at 8:00 p.m. when the closure will resume. The weeks of the closures are as follows: October 18-23, October 25-30 and November 1-6, 2004. After a three-week break, closures will resume November 29-December 4, December 6-11 and December 13-18, 2004. Closures will be in effect from the junction of SR 70/89 (The Greenville Wye) and just prior to Jarbo Gap. Local traffic will be allowed. Work on all bridges will result in intermittent delays of 10-20 minutes. During non-work hours there will be delays of up to a few minutes due to the traffic signals.

This schedule is subject to change based on weather, production rates and unforeseen conditions. The two-week gap in closures is required for concrete cure. The timeframe has increased because additional work is being performed and complete closures are due to the narrow width of the bridge and the work being conducted in the middle strip of the deck.

For more information please contact the Public Information Office at 229-0511.

####

NOTE: An electronic version of this news release is available on the internet at the following web address: http://www.dot.ca.gov/dist2/news_releases.htm

